



Appendix 8-A Potentially contaminated sites within and outside FSL




Figure 8A-1 Stockyard 1 / Potential Cattle Dip Site (DERM 1963)








Figure 8A-2 Stockyard 2 / Potential Cattle Dip Site (DERM 1963)














Figure 8A-4 Stockyard 3 / Potential Cattle Dip Site and Farm House, (DERM 1984)








Figure 8A-5 Stockyard 4 / Potential Cattle Dip Site (DERM 1950)







Figure 8A-6 Stockyard 5 / Potential Cattle Dip Site and Farm House (Google Earth Pro 2010)







Figure 8A-7 Stockyard 6 / Potential Cattle Dip Site and Farm House (Google Earth Pro 2010)







Figure 8A-8 Stockyard 7 / Potential Cattle Dip Site and Buildings (Google Earth Pro 2010)








Figure 8A-9 Stockyard 8 / Potential Cattle Dip Site (Google Earth Pro 2010)







Figure 8A-10 Stockyard 9 / Potential Cattle Dip Site (Google Earth Pro 2010)








Figure 8A-11 Disturbed Land 1 (DERM 1984)







Figure 8A-12 Farm House 1 (Google Earth Pro 2010)







Figure 8A-13 Farm House 2 (Google Earth Pro 2010)







Figure 8A-14 Farm House 4 (Google Earth Pro 2010)







Figure 8A-15 Buildings 1 (Google Earth Pro 2010)







Figure 8A-16 Buildings 2 (Google Earth Pro 2010)







Figure 8A-17 Farm House(Google Earth Pro 2010)







Figure 8A-18 Land parcel listed on EMR under 'Live Stock Dip or Spray Race'. 1 in 100yr Flood Level is to west (left) of blue line.