

# **Hinze Dam Stage 3**

## **Environmental Impact Statement Supplementary Report**

**August 2007**

# Table of Contents

<b>1. Introduction</b>	<b>1-8</b>
1.1 Purpose of Supplementary Report	1-8
1.2 Consultation on EIS	1-8
<b>2. Project Description</b>	<b>2-10</b>
2.1 Overview	2-10
2.2 Revised Project Area	2-10
<b>3. Submission Analysis</b>	<b>3-11</b>
<b>3.1 Project Rationale</b>	<b>3-11</b>
3.1.1 Rationale for Raising of Hinze Dam	3-11
3.1.2 Spillway Options	3-12
3.1.3 Economic Viability of the Project	3-12
3.1.4 Impact Assessment Process	3-13
3.1.5 Use of Modelling in the EIS Preparation	3-13
<b>3.2 Project Description</b>	<b>3-14</b>
3.2.1 Construction Hours	3-14
3.2.2 Clay Borrow Area	3-14
3.2.3 Project Management Structure	3-15
<b>3.3 Project Approvals – ERAs</b>	<b>3-15</b>
3.3.1 ERA 7 – Chemical Storage	3-18
3.3.2 ERA 11 – Petroleum Storage	3-23
3.3.3 ERA 19 – Dredging	3-30
3.3.4 ERA 20 – Extracting Rock or other Material	3-31
3.3.5 ERA 22 – Screening Materials	3-37
3.3.6 ERA 28 – Motor Vehicle Workshop	3-42
3.3.7 ERA 62 – Concrete Batching	3-49
3.3.8 ERA 84 – Regulated Waste Storage	3-58
<b>3.4 Project Approvals – General</b>	<b>3-59</b>
3.4.1 Vegetation Clearing	3-59
3.4.2 Road works on Main Roads	3-60
3.4.3 <i>Water Act 2000</i> Approvals	3-60
3.4.4 Native Title	3-61
3.4.5 Dam Failure Impact Assessment	3-61
3.4.6 Sewage Treatment Facilities	3-61
<b>3.5 Land Contamination</b>	<b>3-61</b>
3.5.1 Methodology of Study	3-61
3.5.2 Impacts of Past Land Uses	3-62
3.5.3 Abandoned Vehicles	3-62
3.5.4 Notifiable Activities	3-62
<b>3.6 Land Use and Infrastructure</b>	<b>3-63</b>
3.6.1 Numinbah Valley Environmental Education Centre	3-63
3.6.2 Land Acquisition	3-63
3.6.3 Recreation Facilities	3-63
<b>3.7 Surface Water Resources and Water Quality</b>	<b>3-63</b>

---

3.7.1	Rainfall Reliability at Hinze dam	3-63
3.7.2	Impacts on Numinbah Valley Environmental Education Centre (NVEEC)	3-66
3.7.3	Water Quality Downstream	3-69
3.7.4	Stream Siltation	3-69
<b>3.8</b>	<b>Terrestrial Ecology</b>	<b>3-69</b>
3.8.1	Project Consideration of Environment	3-69
3.8.2	Impacts to Fauna	3-69
3.8.3	Impacts for Flora	3-71
3.8.4	Compensatory Habitats/Offsets	3-72
3.8.5	Amendments to Figures, Tables and Text	3-73
3.8.6	Environmental Management Plans	3-75
3.8.7	Vegetation Clearing	3-76
3.8.8	Vegetation Protection Orders	3-76
3.8.9	Essential Habitat	3-76
3.8.10	Impact on Upstream Tributaries	3-77
3.8.11	Surveys	3-77
3.8.12	Inundation of Priority Areas	3-77
<b>3.9</b>	<b>Aquatic Ecology</b>	<b>3-78</b>
3.9.1	Fish Passage	3-78
3.9.2	Riparian Habitat Loss	3-82
3.9.3	Recreational and Commercial Fisheries	3-82
3.9.4	Water Quality Impacts	3-83
3.9.5	Middle Nerang Catchment	3-83
3.9.6	Aquatic Ecology Operation EMP	3-84
<b>3.10</b>	<b>Air Quality and Greenhouse Gases</b>	<b>3-85</b>
3.10.1	Modelling Results and Consistency with Guidelines	3-85
3.10.2	Air Quality Monitoring Methodology	3-85
3.10.3	Impact of Dust Deposition on Water Quality in Rain Water Tanks	3-85
3.10.4	Health Impacts of Increased Vehicle Emissions During Construction	3-86
3.10.5	Dust Suppression Activities	3-86
3.10.6	Greenhouse Gas Emissions	3-86
<b>3.11</b>	<b>Noise and Vibration</b>	<b>3-86</b>
3.11.1	Construction Hours of Operation	3-86
3.11.2	Construction Hours Evening Shift	3-86
3.11.3	Old Advancetown Road Access	3-87
3.11.4	Noise Impacts	3-87
3.11.5	Quarry Operations and Blasting	3-90
3.11.6	Vibration Impacts	3-90
3.11.7	Noise Modelling, Monitoring and Environmental Management	3-91
<b>3.12</b>	<b>Transport and Roads</b>	<b>3-92</b>
3.12.1	Existing Traffic	3-92
3.12.2	Construction Stage Traffic	3-96
3.12.3	Mitigation of Construction Traffic Impacts	3-99
3.12.4	Operational Stage Traffic	3-101
3.12.5	Mitigation of Operational Stage Traffic Impacts	3-103
3.12.6	Alternative Access via Old Advancetown Rd	3-104
3.12.7	Partial Embankment Inundation	3-108
3.12.8	Culvert Inundation	3-111

3.12.9	Gold Coast-Springbrook Road Realignment	3-111
3.12.10	Bridge on Pocket Road	3-113
3.12.11	Impacts on Road Pavements During Construction	3-113
3.12.12	Upgrade of Existing Boat Ramps	3-113
<b>3.13</b>	<b>Hazard, Safety and Risk</b>	<b>3-116</b>
3.13.1	Bushfire	3-116
3.13.2	Terrorism/Security	3-116
<b>3.14</b>	<b>Socio-Economic</b>	<b>3-116</b>
3.14.1	Impact on Property Values	3-116
3.14.2	Compensation	3-117
<b>3.15</b>	<b>Cultural Heritage</b>	<b>3-117</b>
3.15.1	Clay Borrow Area – Cultural Heritage	3-117
<b>3.16</b>	<b>Visual Amenity</b>	<b>3-119</b>
3.16.1	Existing Visual Environment	3-119
3.16.2	Visual Assessment – Construction	3-121
3.16.3	Visual Assessment – Operation	3-125
3.16.4	Visual Assessment – Operation	3-126
<b>3.17</b>	<b>Management Plans</b>	<b>3-134</b>
3.17.1	Environmental Management Plans	3-134
3.17.2	Groundwater Monitoring	3-135
3.17.3	Rehabilitation Plans	3-135
<b>3.18</b>	<b>Community Consultation</b>	<b>3-135</b>
<b>4.</b>	<b>Reference List</b>	<b>4-138</b>
<b>Appendix A</b>	<b>Public Submission Summaries</b>	<b>4-139</b>
<b>Appendix B</b>	<b>Noise Assessment</b>	<b>4-161</b>
<b>Appendix C</b>	<b>Surface Water Management Plan</b>	<b>4-162</b>
<b>Appendix D</b>	<b>Amended EIS Figures</b>	<b>4-163</b>
<b>Appendix E</b>	<b>Fish Passage</b>	<b>4-164</b>
<b>Appendix F</b>	<b>Drawings</b>	<b>4-165</b>

## Figures

■	Figure 1 - Site Layout Plan - Location of ERAs	3-17
■	Figure 2 – Site Layout – Concrete Batching Plant and Liquid Nitrogen Storage	3-19
■	Figure 3 - Schematic Diagram of a Vacuum Insulated Tank	3-20
■	Figure 4 - Example of Vacuum Insulated Tanks	3-20
■	Figure 5 – Site Layout – Workshop and Fuel Storage Tanks	3-24
■	Figure 6 - Proposed Self-bunded Fuel Tanks	3-25

■	Figure 7 - Fill Reticulation System	3-26
■	Figure 8 - Fill Point	3-26
■	Figure 9 - Existing Quarry Site	3-32
■	Figure 10 – Site Layout – Crushing and Screening Plant	3-38
■	Figure 11 - Example of a Crushing and Screening Plant	3-40
■	Figure 12 – Oil Water Separator - Schematic Detail and Process Description	3-47
■	Figure 13 - Concrete Washout	3-51
■	Figure 14 Abandoned Vehicles on Lot 234 WD4207	3-62
■	Figure 15 Hinze Dam Annual Rainfall	3-64
■	Figure 16 Hinze Dam Recorded Storage Volume (1999 - 2007)	3-65
■	Figure 17 Hinze Dam Simulated Storage Behaviour (1890-2000)	3-66
■	Figure 18 Numinbah Valley Environmental Education Centre inundation impacts	3-68
■	Figure 19 Existing Peak hour Traffic volumes at Advancetown Rd / Nerang-Murwillumbah Rd intersection – 8 <sup>th</sup> August 2007	3-94
■	Figure 20 Advancetown Road major culvert a chainage 706.4m	3-100
■	Figure 21 Alternative Access Typical Cross-section	3-105
■	Figure 22 Alternative Access Investigated Alignment	3-106
■	Figure 23 Alternative Access Investigated Vertical Alignment	3-107
■	Figure 24 Embankment Inundation Locations	3-109
■	Figure 25 Location of Culvert S-B	3-112
■	Figure 26 Boat Ramp Locations	3-115
■	Figure 27 Trees of Cultural Heritage Significance	3-118
■	Figure 28 Environmental Management Document Map (Construction)	3-134

## Tables

■	Table 1 Hinze Dam EIS Modelling	3-13
■	Table 2 Project Site Clay Resources	3-14
■	Table 3 Spill Response Procedure for Spills on Concrete/Bitumen	3-28
■	Table 4 Spill Response Procedure for Spills on Soils	3-29
■	Table 5 Spill Response Procedure for Spills in Water	3-30

■	Table 6 - Machinery used for Quarry Establishment	3-32
■	Table 7 - Machinery used during Quarry Operation	3-32
■	Table 8 Machinery used during Operation of the Clay Borrow Area	3-34
■	Table 9- Yearly production rates from crushing and screening plant	3-39
■	Table 10 Noise Monitoring Locations	3-43
■	Table 11 Results of Unattended Noise Monitoring	3-44
■	Table 12 External Maximum Instantaneous Noise Level ( $L_{Amax}$ ) (EPA 2004).	3-44
■	Table 13 - Quantity of materials to be processed	3-52
■	Table 14 - Yearly production rate	3-52
■	Table 15 Hinze Dam Rainfall	3-63
■	Table 16 Likelihood of Occurrence of EPBC Listed Flora Species ( <i>Sarcochilus hartmannii</i> )	3-74
■	Table 17 Potential Impacts on Significant Flora ( <i>Randia moorei</i> & <i>Owenia cepiodora</i> )	3-74
■	Table 18 Offset/Compensatory Habitat Targets ('Of Concern' RE 12.3.2)	3-75
■	Table 19 Historical and current character of the Nerang River fish community*	3-80
■	Table 20 Environmental Values for the Waters of the Nerang Catchment	3-83
■	Table 21 Noise Impacts	3-87
■	Table 22 Quarry and Blasting Impacts	3-90
■	Table 23 Vibration Impacts	3-90
■	Table 24 Noise Modelling, Monitoring and Environmental Management	3-91
■	Table 25 Traffic volumes across dam	3-92
■	Table 26 Estimated Additional Weekend Day peak hour traffic volumes – Existing	3-95
■	Table 27 Advancetown Rd/Nerang-Murwillumbah Rd 2007 existing intersection performance	3-96
■	Table 28 Advancetown Road Existing Link Performance	3-96
■	Table 29 Estimated vehicle traffic generated during Construction Phase	3-97
■	Table 30 Estimated daily construction associated traffic along Advancetown Road	3-97
■	Table 31 Additional Peak hour traffic volumes on Advancetown Road during - Construction Phase	3-98
■	Table 32 Advancetown Rd/Nerang-Murwillumbah Rd intersection performance comparison – Construction Phase - weekday	3-98
■	Table 33 Road Link Impact Assessment - Construction Stage - weekday	3-99

■ Table 34 Additional Day peak hour traffic volumes on Avancetown Road – Operational Stage – weekend	3-101
■ Table 35 Advancetown Rd/Nerang-Murwillumbah Rd intersection performance comparison – Operational Phase – Weekend	3-102
■ Table 36 Road Link Impact Assessment – Operational Phase	3-103
■ Table 37 Alternative Access Approximate Key Quantities	3-107
■ Table 38 Alternative Access Issues and Risks	3-107
■ Table 39 Inundation locations and treatments	3-110
■ Table 40 Existing Visual Environment	3-119
■ Table 41 Visual Impacts – Construction	3-123
■ Table 37 Visual Impacts Red Oak Drive – Operation	3-126
■ Table 42 Visual Impacts Red Oak Drive – Operation	3-127
■ Table 43 Visual Impacts Duncan Road & Mottee Court – Operation	3-132